



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Results Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category	Provisional Class	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2018-2019
<b>Gascoyne Region</b>																
Carnarvon (Shire of)	Inlet	CN3/001	Carnarvon Town Beach	-24.898049, 113.640697	1. Program	2013-2018	32	165	B	2852	97	Not Avail	Not Avail		Provide DoH SIR	13
Carnarvon (Shire of)	Inlet	CN3/003	Facsine Beach	-24.883493, 113.65417	1. Program	2011-2015	51	45	B	96	34	Not Avail	Not Avail		Provide DoH SIR	13
Carnarvon (Shire of)	Inlet	CN3/004	Baxter Park Beach	-24.89152, 113.654091	1. Program	2011-2015	48	45	B	700	20	Not Avail	Not Avail		Provide DoH SIR	13
Carnarvon (Shire of)	Inlet	CN3/005	Yacht Club	-24.89233, 113.654028	1. Program	2013-2015	33	30	A	140	12	Not Avail	Not Avail		Provide DoH SIR	13
Carnarvon (Shire of)	Inlet	CN3/045	Fascine Jetty	-24.884065, 113.653027	1. Program	2013-2018	39	50	B	118	35	Not Avail	Not Avail		Provide DoH SIR	13
Carnarvon (Shire of)	Ocean	CN3/046	Pelican Point Beach	-24.897549, 113.638457	1. Program	2013-2018	34	4	A	30	16	Not Avail	Not Avail		Provide DoH SIR	13
Carnarvon (Shire of)	Harbour	CN3/043	Boat Harbour Snapper Jetty	-24.898193, 113.65109	4. Active (Non-core)	2013-2018	36	36	A	95	27	Not Avail	Not Avail			5
Carnarvon (Shire of)	Harbour	CN3/044	Boat Harbour Wharf	-24.899092, 113.650946	4. Active (Non-core)	2011-2015	48	8	A	38	21	Not Avail	Not Avail			5
Carnarvon (Shire of)	Inlet	CN3/002	Carnarvon Town Beach (2)	-24.89784, 113.64085	4. Active (Non-core)	2013-2018	35	20	A	63	19	Not Avail	Not Avail		Provide DoH SIR	13
Carnarvon (Shire of)	Inlet	CN3/006	Yacht Club Marina	-24.894711, 113.653688	4. Active (Non-core)	2013-2015	33	16	A	48	25	Not Avail	Not Avail			5
Carnarvon (Shire of)	Inlet	CN3/041	Northwater DB Drive	-24.881972, 113.65414	4. Active (Non-core)	2011-2015	43	95	B	226	51	Not Avail	Not Avail			5
Carnarvon (Shire of)	Inlet	CN3/042	Northwater Jaaga	-24.88268, 113.649727	4. Active (Non-core)	2013-2018	34	95	B	396	46	Not Avail	Not Avail			5
Carnarvon (Shire of)	River	CN3/047	Chinamans Pool	-24.860979, 113.673522	4. Active (Non-core)	2011-2015	32	720	D	1329	271	Not Avail	Not Avail			5



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Results Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category	Provisional Class	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2018-2019
<b>Gascoyne Region ...</b>																
Exmouth (Shire of)	Canal	EX3/057	Canal Nr Bridge Horwood Side	-21.954736, 114.135727	1. Program	2013-2018	34	40	A	111	29	Moderate	Good (a)		Collect 5-10 stormwater drain samples	13
Exmouth (Shire of) / DoT	Harbour	EX3/050	Small Boat Harbour - Boat Ramp	-21.955913, 114.13953	1. Program	2013-2018	32	28	A	75	26	Low	Very Good		Annual SIR Review	13
Exmouth (Shire of)	Ocean	EX3/051	Exmouth Town Beach	-21.945644, 114.140116	1. Program	2013-2018	27	2	A	23	14	Low	Very Good		Annual SIR Review	13
<b>Goldfields - Esperance Region</b>																
Esperance (Shire of) / DoT	Harbour	ES3/030	Bandy Creek Harbour	-33.831938, 121.933446	1. Program	2013-2018	53	200	B	700	91	Moderate	Good		Collect 5-10 rainfall (24-48hrs) samples	13
Esperance (Shire of)	Ocean	ES3/031	James St Groyne	-33.860941, 121.89603	1. Program	2013-2018	52	90	B	189	51	Moderate	Good		Collect 5-10 stormwater drain samples	13
Esperance (Shire of) / Esperance Port Authority	Ocean	ES3/032	Port Authority Beach	-33.867722, 121.895011	1. Program	2013-2018	51	90	B	195	49	Moderate	Good		Collect 5-10 stormwater drain samples	13
<b>Great Southern Region</b>																
Albany (City of)	Harbour	AC3/009	Boatshed Beach - Princess Royal Harbour	-35.031225, 117.889195	3. Proposed							Not Avail	Not Avail		Provide DoH SIR	13
Albany (City of)	Inlet	AC3/007	Emu Beach - Oyster Harbour	-34.996985, 117.947777	3. Proposed	2014-2015	8	2200	D		145	Not Avail	Not Avail		Provide DoH SIR	13
Albany (City of)	Ocean	AC3/010	Frenchman Bay	-35.092244, 117.94883	3. Proposed							Not Avail	Not Avail		Provide DoH SIR	13
Albany (City of)	Ocean	AC3/032	Ellen Cove (Jetty) - Middleton Beach	-35.025484, 117.918298	3. Proposed							Not Avail	Not Avail		Provide DoH SIR	13



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Results Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category	Provisional Class	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2018-2019
<b>Great Southern Region ...</b>																
Albany (City of)	Harbour	AC3/025	Oyster Harbour - 6021173 - AOH1 - S - Middle	-34.983231, 117.955659	4. Active (Non-core)							Not Avail	Not Avail			5
Albany (City of) / DWER	Harbour	AC3/026	Oyster Harbour - 6021174 - AOH2 - SE	-34.98291, 117.965439	4. Active (Non-core)							Not Avail	Not Avail			5
Albany (City of)/ DWER	Harbour	AC3/027	Oyster Harbour - 6021260 - AOH12 - SW Yak Crk	-34.982958, 117.943254	4. Active (Non-core)							Not Avail	Not Avail			5
Albany (City of)/ DWER	Harbour	AC3/028	Oyster Harbour - 6021176 - AOH4 - NW Bay Rd	-34.962303, 117.954409	4. Active (Non-core)							Not Avail	Not Avail			5
Albany (City of)/ DWER	Harbour	AC3/029	Oyster Harbour - 6021177 - AOH5 - NW - Low Kg	-34.950692, 117.955238	4. Active (Non-core)							Not Avail	Not Avail			5
Albany (City of)/ DWER	River	AC3/030	Oyster Harbour - 6021254 - AOH6 - NE - Kalg Rvr Bdg	-34.948953, 117.977734	4. Active (Non-core)							Not Avail	Not Avail			5
Albany (City of)/ DWER	River	AC3/031	Lower Bridge - 6021063 - Lower King Rvr Bdg	-34.94397, 117.947702	4. Active (Non-core)							Not Avail	Not Avail			5
Cranbrook (Shire of)	Lake	CR3/001	Nunijup Lake	-34.4054, 117.406573	3. Proposed							Moderate	Not Avail		Collect 5-10 rainfall (24-48 hrs) samples	13
Cranbrook (Shire of)	Lake	CR3/002	Lake Poorrarecup	-34.419673, 117.233831	3. Proposed							Low	Not Avail		Annual SIR Review	13
Denmark (Shire of)	Inlet	DK3/051	Wilson Inlet - Yacht Club Gazebo	-34.975896, 117.366096	1. Program	2013-2018	21	85	B	323	41	Not Avail	Not Avail		Provide DoH SIR	13
Denmark (Shire of)	Ocean	DK3/025	Peaceful Bay - Ocean	-35.041714, 116.92976	1. Program	2013-2018	29	50	B	167	27	Moderate	Good		Collect 5-10 stormwater drain samples	13
Denmark (Shire of)	Ocean	DK3/025A	Peaceful Bay - Ocean (South)	-35.042113, 116.929721	1. Program	2013-2018	30	2	A	14	11	Moderate	Good (a)		Collect 5-10 stormwater drain samples	13
Denmark (Shire of)	Ocean	DK3/025B	Peaceful Bay - Ocean (North)	-35.041352, 116.929873	1. Program	2013-2018	30	34	A	140	15	Moderate	Good (a)		Collect 5-10 stormwater drain samples	13



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Results Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category	Provisional Class	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2018-2019
<b>Great Southern Region ...</b>																
Denmark (Shire of)	Bore	DK3/035	Peaceful Bay - Central Ave Bore	-35.039025, 116.926137	4. Active (Non-core)	2013-2018	41		A		10	Not Avail	Not Avail			5
Denmark (Shire of)	Bore	DK3/038	Peaceful Bay - Fourth Ave Bore	-35.038081, 116.926452	4. Active (Non-core)	2013-2018	42		A		10	Not Avail	Not Avail			5
Denmark (Shire of)	Bore	DK3/039	Peaceful Bay - Fith Ave Bore	-35.037803, 116.924256	4. Active (Non-core)	2013-2018	41	90	B	700	19	Not Avail	Not Avail			5
Denmark (Shire of)	Bore	DK3/040	Peaceful Bay - Bore Tap Caravan Park	-35.040626, 116.927578	4. Active (Non-core)	2013-2018	42	18	A	140	10	Not Avail	Not Avail			5
Denmark (Shire of)	Creek	DK3/021	Peaceful Bay - Supply Creek	-35.041304, 116.925934	4. Active (Non-core)	2013-2018	41	3700	D	25934	2951	Not Avail	Not Avail			5
Denmark (Shire of)	Creek	DK3/024	Peaceful Bay - Creek/Drain	-35.041636, 116.929175	4. Active (Non-core)	2013-2018	41	540	D	922	201	Not Avail	Not Avail			5
Denmark (Shire of)	Drain	DK3/023	Peaceful Bay Open Drain - Foot Bridge	-35.041127, 116.928611	4. Active (Non-core)	2013-2018	42	820	D	965	247	Not Avail	Not Avail			5
Denmark (Shire of)	Drain	DK3/026	Peaceful Bay Open Drain - Peppermint Rd	-35.037608, 116.921235	4. Active (Non-core)	2013-2018	9	1700	D	4082	695	Not Avail	Not Avail			5
Denmark (Shire of)	Drain	DK3/027	Peaceful Bay Drain - Cnr West Ave/Fourth Ave	-35.037982, 116.923731	4. Active (Non-core)	2013-2018	13	560	D	673	181	Not Avail	Not Avail			5
Denmark (Shire of)	Drain	DK3/028	Peaceful Bay Drain - Cnr East Ave/Fourth Ave	-35.037566, 116.927596	4. Active (Non-core)	2013-2018	11	2850	D	14432	1811	Not Avail	Not Avail			5
Denmark (Shire of)	Drain	DK3/029	Peaceful Bay Drain - Caravan Park	-35.04009, 116.929362	4. Active (Non-core)	2013-2018	8	440	C	405	133	Not Avail	Not Avail			5
Denmark (Shire of)	Drain	DK3/042	Nornalup - Drain Outlet	-34.990902, 116.815937	4. Active (Non-core)	2013-2018	41	480	C	900	190	Not Avail	Not Avail			5
Denmark (Shire of)	Reservoir	DK3/022	Peaceful Bay - Water Supply Dam	-35.040871, 116.927578	4. Active (Non-core)	2013-2018	42	1000	D	2938	460	Not Avail	Not Avail			5
Denmark (Shire of)	Tap	DK3/031	East Ave (Lot 163) - Garden Tap	-35.039597, 116.928095	4. Active (Non-core)	2013-2018	42	105	B	216	56	Not Avail	Not Avail			5



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Results Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category	Provisional Class	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2018-2019
<b>Great Southern Region ...</b>																
Denmark (Shire of)	Tap	DK3/036	Peaceful Bay - Third Ave (Lot 92) Garden Tap	-35.038736, 116.92496	4. Active (Non-core)	2013-2018	42	50	B	131	33	Not Avail	Not Avail			5
Denmark (Shire of)	Creek	DK3/052	Creek - Inlet Drive Bridge 3	-34.9739, 117.3653	5. Inactive (Non-core)	2012-2013	13	520	D	586	164	Not Avail	Not Avail			0
Denmark (Shire of)	Inlet	DK3/055	Wilson Inlet - Springdale Beach 6	-34.969435, 117.387766	5. Inactive (Non-core)	2012-2013	25	100	B	333	52	Not Avail	Not Avail		Provide DoH SIR	5
Denmark (Shire of)	Inlet	DK3/050	Wilson Inlet - Ocean Beach Caravan Park	-35.02107, 117.327082	6. Review	2012-2014	26	45	B	700	10	Not Avail	Not Avail		Provide DoH SIR	13
Denmark (Shire of)	Inlet	DK3/053	Wilson Inlet - Rivermouth Caravan Park	-34.970279, 117.369053	6. Review	2013-2018	21	210	C	405	93	Not Avail	Not Avail		Provide DoH SIR	13
Denmark (Shire of)	River	DK3/054	Denmark River - Berridge Park	-34.959994, 117.357211	6. Review	2013-2018	21	1100	D	2086	403	Not Avail	Not Avail		Provide DoH SIR	13
Katanning (Shire of)	Lake	KT3/013	Lake Ewlyamartup	-33.693108, 117.736472	3. Proposed							Moderate	Not Avail		Collect 10 stormwater, upstream riverine & rainfall (24-48hrs) samples	13
<b>Kimberley Region</b>																
Broome (Shire of)	Ocean	BM3/070	Gantheaume Point	-17.972379, 122.187052	2. New	2017-2018	9	260	C	315	98	Not Avail	Not Avail		Provide DoH SIR	13
Broome (Shire of)	Ocean	BM3/071	Cable Beach	-17.931514, 122.209044	2. New	2017-2018	10	390	C	856	168	Not Avail	Not Avail		Provide DoH SIR	13
Broome (Shire of)	Ocean	BM3/073	Town Beach Roebuck Bay	-17.971442, 122.235969	2. New	2017-2018	12	430	C	484	141	Not Avail	Not Avail		Provide DoH SIR	13
Broome (Shire of)	Ocean	BM3/074	Streeters' Jetty Roebuck Bay	-17.953451, 122.24599	2. New	2018	8	800	D	973	246	Not Avail	Not Avail		Provide DoH SIR	13
Broome (Shire of) / Broome Port Authority	Ocean	BM3/072	Port Authority Beach	-18.001231, 122.209594	3. Proposed							Not Avail	Not Avail		Provide DoH SIR	13



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Results Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category	Provisional Class	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2018-2019
<b>Kimberley Region ...</b>																
Halls Creek (Shire of)	Lake	HC3/002	Lake Komaterpila	-18.346907, 127.823112	3. Proposed							Not Avail	Not Avail		Provide DoH SIR	13
Halls Creek (Shire of)	Pool	HC3/001	Caroline Pool	-18.226293, 127.758536	3. Proposed							Not Avail	Not Avail		Provide DoH SIR	13
Halls Creek (Shire of)	River	HC3/003	Palm Springs	-18.420166, 127.845376	3. Proposed							Not Avail	Not Avail		Provide DoH SIR	13
Halls Creek (Shire of)	Stream	HC3/004	Sawpit Gorge	-18.424952, 127.820059	3. Proposed							Not Avail	Not Avail		Provide DoH SIR	13
<b>Midwest Region</b>																
Greater Geraldton (City of)	Ocean	GE3/001	Town Beach Jetty	-28.772771, 114.60733	1. Program	2013-2018	32	2	A	12	11	High	Good (a)		Collect 5-10 stormwater drain samples	13
Greater Geraldton (City of)	Ocean	GE3/003	Point Moore North	-28.782423, 114.577166	1. Program	2013-2018	31	30	A	81	26	Moderate	Good (a)		Collect 5-10 rainfall (24-48hrs) samples	13
Greater Geraldton (City of)	Ocean	GE3/005	Separation Point	-28.78948, 114.59664	1. Program	2012-2018	20	150	B	848	78	Moderate	Good		Collect 5-10 rainfall (24-48hrs) samples	13
Greater Geraldton (City of)	Ocean	GE3/006	Back Beach	-28.79514, 114.611337	1. Program	2013-2018	31	30	A	140	14	Moderate	Good (a)		Collect 5-10 rainfall (24-48hrs) samples	13
Greater Geraldton (City of)	Ocean	GE3/008	Marina North	-28.763243, 114.614429	1. Program	2013-2018	30	3	A	29	17	Moderate	Good (a)		Collect 5-10 stormwater drain samples	13
Greater Geraldton (City of)	Ocean	GE3/010	Saint Georges	-28.745934, 114.617895	1. Program	2013-2018	32	30	A	93	21	Moderate	Good (a)		Collect 5-10 rainfall (24-48hrs) samples	13
Greater Geraldton (City of)	Ocean	GE3/012	Sunset Beach - Triton Place	-28.721125, 114.6192	1. Program	2013-2018	32	34	A	100	23	Not Avail	Not Avail		Provide DoH SIR	13
Greater Geraldton (City of)	Ocean	GE3/021	Pages Beach North	-28.776499, 114.583602	1. Program	2013-2018	34	290	C	1705	170	Moderate	Poor		Collect 5-10 stormwater drain samples	13
Greater Geraldton (City of)	Ocean	GE3/022	Tarcoola Beach	-28.81802, 114.62311	1. Program	2013-2018	29	5	A	30	13	Very Low	Very Good		Annual SIR Review	13



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Results Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category	Provisional Class	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2018-2019
<b>Midwest Region ...</b>																
Greater Geraldton (City of)	Ocean	GE3/023	Greenough Beach	-28.861882, 114.63482	1. Program	2013-2018	29	9	A	38	12	Moderate	Good (a)		Collect 5-10 rainfall (24-48hrs) samples	13
Greater Geraldton (City of)	Ocean	GE3/026	Drummonds Cove	-28.670796, 114.611879	1. Program	2011-2014	23	45	B	106	32	Low	Good		Annual SIR Review	13
Greater Geraldton (City of)	River	GE3/024	Greenough River Mouth	-28.862921, 114.638199	1. Program	2013-2018	33	160	B	244	73	High	Fair (a)		Collect 5-10 rainfall (24-48hrs) samples	13
Greater Geraldton (City of)	River	GE3/025	Ellendale Pool	-28.860916, 114.973733	1. Program	2013-2018	33	340	C	384	118	High	Poor		Collect 5-10 rainfall (24-48hrs) samples	13
Irwin (Shire of) / DoT	Harbour	IR3/080	Marina (Boat Ramp)	-29.274863, 114.91862	1. Program	2011-2017	27	30	A	140	10	Not Avail	Not Avail		Provide DoH SIR	13
Irwin (Shire of)	Ocean	IR3/001	Nun's Pool	-29.261797, 114.920922	1. Program	2011-2017	27	75	B	700	10	Moderate	Good		Collect 5-10 riverine & site samples	13
Irwin (Shire of)	Ocean	IR3/060	South Beach	-29.283478, 114.919042	1. Program	2011-2017	27	14	A	49	18	Not Avail	Not Avail		Provide DoH SIR	13
Irwin (Shire of)	Ocean	IR3/070	Granny's Beach	-29.271023, 114.92187	1. Program	2011-2017	27	18	A	60	18	Not Avail	Not Avail		Provide DoH SIR	13
<b>Peel Region</b>																
Mandurah (City of)	Canal	MD3/330	Hall Park	-32.533631, 115.716415	1. Program	2013-2018	62	5	A	30	11	Low	Very Good		Annual SIR Review	5
Mandurah (City of)	Canal	MD3/410	North Port	-32.596808, 115.639226	1. Program	2013-2018	62	45	B	122	29	Moderate	Good		Collect 5-10 stormwater samples	13
Mandurah (City of)	Estuary	MD3/411	Eastern Foreshore	-32.530706, 115.71955	1. Program	2013-2018	64	60	B	128	40	Moderate	Good		Collect 5-10 stormwater samples	13
Mandurah (City of)	Marina	MD3/310	Marina Beach	-32.525389, 115.717531	1. Program	2012-2018	78	3	A	28	15	Low	Very Good		Annual SIR Review	5
Mandurah (City of)	Ocean	MD3/120	Falcon Beach	-32.579771, 115.65221	1. Program	2012-2018	78	18	A	57	21	Low	Good (a)		Annual SIR Review	5
Mandurah (City of)	Ocean	MD3/155	Halls Head Parade	-32.520261, 115.705116	1. Program	2012-2018	78	80	B	199	45	Low	Good		Annual SIR Review	5
Mandurah (City of)	Ocean	MD3/315	Town Beach	-32.519516, 115.724056	1. Program	2012-2018	78	20	A	64	18	Low	Very Good		Annual SIR Review	5



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Results Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category	Provisional Class	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2018-2019
<b>Peel Region ...</b>																
Mandurah (City of)	Canal	MD3/280A	East Port	-32.607155, 115.646243	4. Active (Non-core)	2013-2018	24	14	A	47	20	Not Avail	Not Avail			5
Mandurah (City of)	Canal	MD3/280B	East Port	-32.601145, 115.650012	4. Active (Non-core)	2013-2018	25	55	B	117	38	Not Avail	Not Avail			5
Mandurah (City of)	Canal	MD3/375A	Mariners Cove	-32.554095, 115.733446	4. Active (Non-core)	2013-2018	26	18	A	55	22	Not Avail	Not Avail			5
Mandurah (City of)	Canal	MD3/375B	Mariners Cove	-32.550549, 115.732398	4. Active (Non-core)	2014-2018	21	105	B	330	54	Not Avail	Not Avail			5
Mandurah (City of)	Canal	MD3/401	Aztec Island	-32.542958, 115.709397	4. Active (Non-core)	2013-2018	26	3	A	26	14	Not Avail	Not Avail			5
Mandurah (City of)	Canal	MD3/403	Monterey Bay	-32.537982, 115.710208	4. Active (Non-core)	2013-2018	26	30	A	140	10	Not Avail	Not Avail			5
Mandurah (City of)	Canal	MD3/404	Leslie Street Boat Ramp	-32.547972, 115.729858	4. Active (Non-core)	2013-2018	27	85	B	387	40	Not Avail	Not Avail			5
Mandurah (City of)	Estuary	MD3/200	Mary Street Lagoon	-32.525418, 115.708011	4. Active (Non-core)	2013-2018	32	2	A	17	12	Not Avail	Not Avail			5
Mandurah (City of)	Estuary	MD3/400	Southport	-32.605765, 115.636234	4. Active (Non-core)	2013-2018	37	2	A	23	13	Not Avail	Not Avail			5
Mandurah (City of)	Estuary	MD3/402	Henry Sutton Grove	-32.530255, 115.71314	4. Active (Non-core)	2013-2018	26	2	A	18	12	Not Avail	Not Avail			5
Mandurah (City of)	Marina	MD3/206	Mandurah Quay Marina	-32.559138, 115.70948	4. Active (Non-core)	2013-2018	26	2	A	13	11	Not Avail	Not Avail			5
Mandurah (City of)	Marina	MD3/405	Mandurah Ocean Marina	-32.523946, 115.719782	4. Active (Non-core)	2013-2018	26	6	A	34	15	Not Avail	Not Avail			5
Mandurah (City of)	Ocean	MD3/095	Tim`s Thicket	-32.653048, 115.61459	4. Active (Non-core)	2013-2018	8	45	B	700	10	Not Avail	Not Avail			5
Mandurah (City of)	Ocean	MD3/100	Melrose Boat Ramp	-32.634396, 115.618829	4. Active (Non-core)	2013-2018	8	3	A	26	14	Not Avail	Not Avail			5
Mandurah (City of)	Ocean	MD3/105	Pyramids Beach	-32.602718, 115.629067	4. Active (Non-core)	2013-2018	28	36	A	140	10	Not Avail	Not Avail			5





## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Results Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category	Provisional Class	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2018-2019
<b>Peel Region ...</b>																
Mandurah (City of)	Ocean	MD3/110	Westview Parade (Avalon)	-32.592582, 115.637482	4. Active (Non-core)	2013-2018	28	30	A	140	10	Not Avail	Not Avail			5
Mandurah (City of)	Ocean	MD3/150	Blue Bay Leighton Road	-32.524469, 115.696717	4. Active (Non-core)	2013-2018	26	5	A	140	10	Not Avail	Not Avail			5
Mandurah (City of)	Ocean	MD3/165	Orion Road	-32.50955, 115.732001	4. Active (Non-core)	2013-2018	28	2	A	24	14	Low	Very Good		Annual SIR Review	5
Mandurah (City of)	Ocean	MD3/175	Eros Place San Remo	-32.486346, 115.743062	4. Active (Non-core)	2013-2018	28	8	A	37	14	Low	Very Good		Annual SIR Review	5
Mandurah (City of)	Ocean	MD3/180	Madora Beach	-32.469157, 115.746114	4. Active (Non-core)	2013-2018	28	2	A	17	10	Moderate	Good (a)		Collect 5-10 rainfall (24-48hrs) samples	5
Mandurah (City of)	Ocean	MD3/135	Gretel Road	-32.56693, 115.666368	5. Inactive (Non-core)	2010-2013	17	16	A	140	10	Not Avail	Not Avail			5
Mandurah (City of)	Ocean	MD3/145	Janis Street	-32.529, 115.693566	5. Inactive (Non-core)	2010-2013	17	38	A	140	29	Not Avail	Not Avail			5
Mandurah (City of)	Canal	MD3/287	North Port		6. Review	2013-2018	20	80	B	700	22	Not Avail	Not Avail			5
Murray (Shire of)	River	MY3/002	Ravenswood Hotel - Murray River	-32.5855, 115.8268	1. Program	2013-2018	63	105	B	145	56	Moderate	Good		Collect 5-10 upstream riverine & rainfall (24-48hrs) samples	13
Murray (Shire of)	River	MY3/003	Murray River Bend	-32.597313, 115.833929	1. Program	2013-2018	63	140	B	1793	74	Moderate	Good		Collect 5-10 upstream riverine & rainfall (24-48hrs) samples	13
Murray (Shire of)	River	MY3/005	Pinjarra Boat Ramp	-32.624834, 115.874457	1. Program	2013-2018	64	420	C	334	122	Moderate	Poor		Collect 5-10 rainfall (24-48hrs) samples	13
Murray (Shire of)	River	MY3/007	Dwellingup Bridge	-32.7623, 116.0763	1. Program	2013-2018	63	100	B	124	54	Moderate	Good		Collect 5-10 upstream riverine & rainfall (24-48hrs) samples	13
Murray (Shire of)	River	MY3/008	Delta Drive	-32.5849, 115.7949	1. Program	2013-2018	63	28	A	66	30	Moderate	Good (a)		Collect 5-10 rainfall (24-48hrs) samples	13



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Results Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category	Provisional Class	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2018-2019
<b>Peel Region ...</b>																
Murray (Shire of)	River	MY3/009	Lucie Hunter Park	-32.585231, 115.779992	1. Program	2013-2018	64	105	B	146	56	Moderate	Good		Collect 5-10 rainfall (24-48hrs) samples	13
Murray (Shire of)	River	MY3/014	Baden Powell (2) Steps	-32.771706, 116.084954	1. Program	2013-2018	63	230	C	348	97	Low	Follow up (b)		Collect 5-10 rainfall (24-48hrs) samples	13
Murray (Shire of)	River	MY3/020	Tatham Rd Jetty	-32.577673, 115.810278	1. Program	2013-2018	65	20	A	53	27	Moderate	Good (a)		Collect 5-10 rainfall (24-48hrs) samples	13
Murray (Shire of)	Inlet	MY3/015	Herron Point	-32.739070, 115.710767	3. Proposed							Not Avail	Not Avail		Provide DoH SIR	13
Murray (Shire of)	River	MY3/006	Coolup Bridge	-32.73503, 115.89988	3. Proposed	2017-2018	12	2000	D	3824	716	Moderate	Poor		Collect 5-10 upstream riverine & rainfall (24-48hrs) samples	13
Murray (Shire of)	Inlet	MY3/018	Coopers Mill	-32.575917, 115.765693	5. Inactive (Non-core)	2012-2017	60	65	B	846	41	Low	Good			0
Murray (Shire of) / DBCA	River	MY3/021	Scarp Pool	-32.764576, 115.998208	5. Inactive (Non-core)	2013-2018	64	75	B	120	46	Low	Good			0
Waroona (Shire of)	Lake	WR3/001	Drakesbrook Dam / Lake Moyanup	-32.858754, 115.951325	1. Program	2013-2018	21	800	D	2720	396	Moderate	Poor		Collect 5-10 rainfall (24-48hrs) samples	13
Waroona (Shire of) / DBCA, DoT	Lake	WR3/002	Waroona Dam / Lake Navarino	-32.851049, 115.990144	1. Program	2012-2017	11	70	B	246	35	Moderate	Good		Collect 5-10 upstream riverine & rainfall (24-48hrs) samples	13



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Results Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category	Provisional Class	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2018-2019
<b>South West Region</b>																
Augusta-Margaret River (Shire of)	Inlet	AM3/023	Hardy Inlet - Turner Caravan Park	-34.32322, 115.16486	1. Program	2013-2018	65	360	C	606	143	Not Avail	Not Avail		Provide DoH SIR	13
Augusta-Margaret River (Shire of)	Ocean	AM3/012	Gnarabup Beach (Jetty)	-33.99016, 114.9908	1. Program	2012-2018	71	60	B	276	28	Low	Good		Annual SIR Review	5
Augusta-Margaret River (Shire of)	Ocean	AM3/014	Gracetown Beach	-33.86435, 114.98647	1. Program	2012-2018	72	8	A	37	15	Low	Very Good		Annual SIR Review	5
Augusta-Margaret River (Shire of)	Ocean	AM3/016	Flinders Bay - Redman Brook	-34.34317, 115.16872	1. Program	2013-2018	67	18	A	86	10	Moderate	Good (a)		Collect 5-10 rainfall (within 24-48hrs) & riverine samples	13
Augusta-Margaret River (Shire of)	River	AM3/001	Margaret River - Canoe Landing	-33.96951, 114.988891	1. Program	2012-2018	76	130	B	286	65	Low	Good		Annual SIR Review	5
Augusta-Margaret River (Shire of)	River	AM3/002	Margaret River - Rivermouth	-33.971092, 114.987313	1. Program	2013-2018	54	130	B	202	63	Moderate	Good		Collect 5-10 rainfall (24-48hrs) samples	13
Augusta-Margaret River (Shire of)	River	AM3/006	Margaret River - Barrett St Weir	-33.94814, 115.08243	1. Program	2013-2018	69	140	B	211	66	High	Fair (a)		Collect 5-10 rainfall (24-48hrs) samples	13
Augusta-Margaret River (Shire of)	River	AM3/044	Margaret River - Rendall Cl Weir	-33.949358, 115.086087	1. Program	2013-2018	52	24	A	66	24	Moderate	Good (a)		Collect 5-10 rainfall (24-48hrs) samples	13
Augusta-Margaret River (Shire of)	River	AM3/038	Blackwood River - Alexandra Bridge	-34.164632, 115.183434	2. New							Not Avail	Not Avail		Provide DoH SIR	13
Augusta-Margaret River (Shire of)	Drain	AM3/022	Colour Patch Drain Foreshore	-34.324404, 115.167991	4. Active (Non-core)	2013-2018	11	26	A	71	25	Not Avail	Not Avail			5



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Results Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category	Provisional Class	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2018-2019
<b>South West Region ...</b>																
Bridgetown-Greenbushes (Shire of)	Pool	BS3/011	Greenbushes Pool – Jetty West	-33.849547, 116.046296	3. Proposed							Moderate	Not Avail		Collect 5-10 rainfall (24-48hrs) samples	13
Bridgetown-Greenbushes (Shire of)	Pool	BS3/012	Greenbushes Pool – Jetty East	-33.849626, 116.046825	3. Proposed							Moderate	Not Avail		Collect 5-10 rainfall (24-48hrs) samples	13
Bridgetown-Greenbushes (Shire of)	River	BS3/006	Blackwood River - Bridge	-33.968129, 116.133683	3. Proposed							Moderate	Not Avail		Collect 5-10 rainfall (24-48hrs) samples	13
Bridgetown-Greenbushes (Shire of)	River	BS3/010	Blackwood River - Steps	-33.970747, 116.136272	3. Proposed							Moderate	Not Avail		Collect 5-10 rainfall (24-48hrs) samples	13
Bunbury (City of)	Harbour	BC3/001	Jetty Bath West	-33.31558, 115.63829	1. Program	2013-2018	53	65	B	202	36	Moderate	Good		Collect 5-10 rainfall (24-48hrs) samples	13
Bunbury (City of)	Ocean	BC3/012	Koombana Beach	-33.31949, 115.64565	1. Program	2013-2018	49	24	A	69	24	Moderate	Good (a)		Collect 5-10 rainfall (24-48hrs) samples	13
Bunbury (City of)	Ocean	BC3/017	Surf Club Beach	-33.32742, 115.62927	1. Program	2012-2018	64	2	A	30	10	Moderate	Good (a)		Collect 5-10 rainfall (24-48hrs) samples	5
Bunbury (City of)	Ocean	BC3/018	Hungry Hollow	-33.33371, 115.62703	1. Program	2013-2018	52	40	A	140	10	Moderate	Good (a)		Collect 5-10 rainfall (24-48hrs) samples	13
Bunbury (City of)	Ocean	BC3/025	Ski Beach	-33.319, 115.64005	1. Program	2012-2018	64	22	A	68	19	Moderate	Good (a)		Collect 5-10 rainfall (within 24hrs) & Riverine samples	5
Bunbury (City of)	Drain	BC3/028	Queens Gardens	-33.3260028, 115.641442	4. Active (Non-core)	2016-2018	18	4600	D		4981	Not Avail	Not Avail			5
Bunbury (City of)	Estuary	BC3/002	Estuary Plug	-33.320967, 115.641159	4. Active (Non-core)	2016-2018	9	55	B	700	42	Not Avail	Not Avail			5
Bunbury (City of)	Estuary	BC3/003	Rowing Club	-33.324674, 115.64231	4. Active (Non-core)	2016-2018	11	340	C	930	158	Not Avail	Not Avail			5



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Results Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category	Provisional Class	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2018-2019
<b>South West Region ...</b>																
Bunbury (City of)	Estuary	BC3/004	Bunbury Yacht Club	-33.326464, 115.64709	4. Active (Non-core)	2013-2018	8	210	C	730	106	Not Avail	Not Avail			5
Bunbury (City of)	Estuary	BC3/005	Meredith Creek	-33.327144, 115.648331	4. Active (Non-core)	2013-2018	19	115	B	396	57	Not Avail	Not Avail			5
Bunbury (City of)	Estuary	BC3/006	Parade Hotel	-33.327536, 115.654558	4. Active (Non-core)	2013-2018	17	75	B	178	43	Not Avail	Not Avail			5
Bunbury (City of)	Estuary	BC3/007	Sofilas	-33.328099, 115.659039	4. Active (Non-core)	2013-2018	17	175	B	822	92	Not Avail	Not Avail			5
Bunbury (City of)	Estuary	BC3/010	Turkey Point	-33.306184, 115.674212	4. Active (Non-core)	2013-2018	6					Not Avail	Not Avail			5
Bunbury (City of)	Estuary	BC3/026	Sykes Foreshore	-33.323328, 115.643394	4. Active (Non-core)	2016-2018	18	145	B	352	71	Not Avail	Not Avail		Provide DoH SIR	5
Bunbury (City of)	Estuary	BC3/027	Canoe Launch	-33.321661, 115.639896	4. Active (Non-core)	2016-2018	19	210	C	508	100	Not Avail	Not Avail		Provide DoH SIR	5
Bunbury (City of)	Harbour	BC3/021	Harbour East	-33.31376, 115.640622	4. Active (Non-core)	2013-2018	6					Not Avail	Not Avail			5
Bunbury (City of)	Harbour	BC3/022	Harbour West	-33.311596, 115.63806	4. Active (Non-core)	2013-2018	6					Not Avail	Not Avail			5
Bunbury (City of)	River	BC3/008	Preston River	-33.326701, 115.671439	4. Active (Non-core)	2013-2018	6					Not Avail	Not Avail			5
Bunbury (City of)	River	BC3/009	Collie River	-33.309425, 115.696352	4. Active (Non-core)	2013-2018	6					Not Avail	Not Avail			5
Bunbury (City of)	Drain	BC3/030	Blair St Canal	-33.330719, 115.642928	5. Inactive (Non-core)	2016	2					Not Avail	Not Avail			5
Bunbury (City of)	Drain	BC3/023	Meredith Creek Compensation Basin	-33.328163, 115.647122	6. Review							Not Avail	Not Avail			5
Bunbury (City of)	Drain	BC3/029	Queens Pump	-33.325747, 115.641875	6. Review							Not Avail	Not Avail			5



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Results Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category	Provisional Class	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2018-2019
<b>South West Region ...</b>																
Busselton (City of)	Ocean	BN3/023	Margaret Street Beach (Site 8)	-33.650749, 115.324495	1. Program	2013-2018	57	105	B	289	55	Moderate	Good		Collect 5-10 rainfall (24-48hrs) samples	13
Busselton (City of)	Ocean	BN3/024	Scout Beach (Site 6)	-33.655705, 115.234292	1. Program	2013-2018	57	85	B	6912	16	Moderate	Good		Collect 5-10 rainfall (24-48hrs) samples	13
Busselton (City of)	Ocean	BN3/025	Forth Street Beach (Site 7)	-33.656216, 115.248267	1. Program	2013-2018	56	95	B	450	47	Moderate	Good		Collect 5-10 rainfall (24-48hrs) samples	13
Busselton (City of)	Ocean	BN3/028	Busselton Jetty Ocean 9	-33.644157, 115.344108	1. Program	2013-2018	56	470	C	48940	858	Moderate	Poor		Collect 5-10 rainfall (24-48hrs) samples	13
Busselton (City of)	Creek	BN3/022	Margaret St - Creek	-33.651729, 115.32365	4. Active (Non-core)	2014-2018	37	980	D	898	254	Not Avail	Not Avail			5
Busselton (City of)	Creek	BN3/027	Forth St - Creek	-33.65705, 115.24761	4. Active (Non-core)	2014-2018	36	130	B	283	66	Not Avail	Not Avail			5
Busselton (City of) / DWER	Creek	BN3/043	Wonnerup Floodgate	-33.619346, 115.41385	4. Active (Non-core)	2015-2018	40	34	A	77	30	Not Avail	Not Avail			5
Busselton (City of) / DWER	Creek	BN3/044	Wonnerup Inlet Road Bridge	-33.61663, 115.420272	4. Active (Non-core)	2015-2018	41	780	D	3515	439	Not Avail	Not Avail			5
Busselton (City of)	Drain	BN3/021	Margaret St - Drain	-33.65324, 115.32367	4. Active (Non-core)	2014-2018	37	680	D	81803	1638	Not Avail	Not Avail			5
Busselton (City of)	Marina	BN3/355	Port Geographe - Swimming Lagoon	-33.629892, 115.389677	4. Active (Non-core)	2015-2018	29	12	A	140	10	Not Avail	Not Avail			5
Busselton (City of) / DWER	Ocean	BN3/045	Wonnerup Inlet Ocean Mouth	-33.610202, 115.423175	4. Active (Non-core)	2015-2018	26	40	A	84	35	Not Avail	Not Avail			5
Capel (Shire of)	Ocean	CP3/001	Forrest Beach	-33.57244, 115.46048	1. Program	2013-2018	30	740	D	4548	483	Moderate	Poor		Collect 5-10 rainfall (24-48 hrs) samples	13
Capel (Shire of)	Ocean	CP3/002	Peppermint Grove Beach	-33.527373, 115.504204	1. Program	2013-2018	30	60	B	252	26	Moderate	Good		Collect 5-10 rainfall (24-48 hrs) samples	13
Capel (Shire of)	Ocean	CP3/003	Minninup Beach	-33.451544, 115.575228	1. Program	2013-2018	30	250	C	1453	143	Moderate	Poor		Collect 5-10 rainfall (24-48 hrs) samples	13



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Results Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category	Provisional Class	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2018-2019
<b>South West Region ...</b>																
Capel (Shire of)	Ocean	CP3/004	Dalyellup Beach	-33.404978, 115.600615	1. Program	2013-2018	29	80	B	397	37	Moderate	Good		Collect 5-10 rainfall (24-48 hrs) samples	13
Capel (Shire of)	River	CP3/005	Preston River - Boyanup	-33.478692, 115.733701	1. Program	2012-2018	38	2100	D	1257	385	High	Very Poor		Recommend permanent warning sign	5
Capel (Shire of)	River	CP3/006	Capel River - Mallokup Bridge	-33.519698, 115.537251	1. Program	2013-2018	30	90	B	142	50	High	Poor		Collect 5-10 rainfall, upstream Riverine + regular site samples	13
Capel (Shire of)	Ocean	CP3/008	North Dalyellup Beach	-33.397131, 115.603824	2. New	2013-2018	8	14	A	140	10	Not Avail	Not Avail		Provide DoH SIR	13
Capel (Shire of)	Ocean	CP3/007	Water Corp Dalyellup Beach	-33.382122, 115.609281	4. Active (Non-core)	2015-2017	6					Not Avail	Not Avail			5
Collie (Shire of) / Dept. of Planning, Lands & Heritage	Lake	CI3/003	Black Diamond Recreational Water Area	-33.34257, 116.092729	1. Program	2015-2018	31	2	A	14	11	Low	Very Good		Annual SIR Review	13
Collie (Shire of)/ DBCA	Lake	CI3/004	Stockton Lake	-33.384219, 116.228083	1. Program	2016-2018	20		A		10	Low	Very Good		Annual SIR Review	13
Collie (Shire of) / DBCA	Reservoir	CI3/001	Potters Gorge - Wellington Dam	-33.390301, 115.983908	1. Program	2015-2017	4					Low	Not Avail		Collect 5-10 rainfall (24-48hrs) samples	13
Collie (Shire of) / DBCA	River	CI3/002	Honeymoon Pool - Preston River	-33.379581, 115.938206	1. Program	2015-2017	10	30	A	63	32	Moderate	Good (a)		Collect 5-10 rainfall (24-48hrs) samples	13
Collie (Shire of)	River	CI3/005	Minninup Pool - Front Parking Area	-33.376853, 116.138084	1. Program	2016-2018	18	2000	D	6668	982	Moderate	Poor		Collect 5-10 rainfall (24-48hrs) samples	13
Collie (Shire of) / DBCA	Lake	CI3/008	Lake Kepwari Beach	-33.457582, 116.232609	2. New							Moderate	Not Avail		Collect 5-10 rainfall (24-48hrs) samples	13
Collie (Shire of) / DBCA	Lake	CI3/010	Lake Kepwari North Outlet	-33.456461, 116.23143	2. New							Moderate	Not Avail		Collect 5-10 rainfall (24-48hrs) samples	13
Collie (Shire of) / DBCA	Lake	CI3/009	Lake Kepwari Boat Ramp	-33.459739, 116.233246	3. Proposed							Moderate	Not Avail		Collect 5-10 rainfall (24-48hrs) samples	13
Collie (Shire of) / Dept. of Planning, Lands & Heritage	Lake	CI3/011	Black Diamond Lake - Side Parking Area	-33.342633, 116.091694	3. Proposed							Low	Not Avail		Annual SIR Review	13



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Results Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category	Provisional Class	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2018-2019
<b>South West Region ...</b>																
Collie (Shire of)	River	CI3/006	Minninup Pool - Stone Stairwell	-33.377038, 116.137753	4. Active (Non-core)	2016-2018	13	220	C	462	100	Moderate	Poor		Collect 5-10 rainfall (24-48hrs) samples	13
Collie (Shire of)	River	CI3/007	Minninup Pool - Side Parking Area	-33.377727, 116.139517	4. Active (Non-core)	2016-2018	10	115	B	194	58	Moderate	Good		Collect 5-10 rainfall (24-48hrs) samples	13
Donnybrook-Balingup (Shire of) / DBCA, DoT	Reservoir	DB3/015	Glen Mervyn Dam - NE	-33.49363, 116.101592	3. Proposed							Moderate	Not Avail		Collect 5-10 rainfall (24-48 hrs) samples	13
Donnybrook-Balingup (Shire of) / DBCA, DoT	Reservoir	DB3/016	Glen Mervyn Dam - Campsite SW	-33.498608, 116.097755	3. Proposed							Moderate	Not Avail		Collect 5-10 rainfall (24-48 hrs) samples	13
Donnybrook-Balingup (Shire of)	River	DB3/013	Preston River - Donnybrook Amphitheatre	-33.575903, 115.826496	4. Active (Non-core)	2014-2018	10	260	C	211	87	Moderate	Poor			5
Donnybrook-Balingup (Shire of)	River	DB3/014	Preston River - Footbridge	-33.57437, 115.825772	4. Active (Non-core)	2014	1					Moderate	Not Avail			5
Harvey (Shire of)/ DBCA	Lake	HA3/027	Lake Brockman Boat Ramp	-33.002994, 115.971344	1. Program	2014-2018	31	34	A	96	25	Moderate	Good (a)		Collect 5-10 rainfall (24-48hrs) & riverine samples	13
Harvey (Shire of)	Ocean	HA3/020	Myalup Beach	-33.103452, 115.686984	1. Program	2013-2018	37	2	A	17	11	Not Avail	Not Avail		Provide DoH SIR	13
Harvey (Shire of)	Ocean	HA3/021	Binningup Beach	-33.148933, 115.685686	1. Program	2013-2018	37	75	B	700	10	Moderate	Good (a)		Collect 5-10 rainfall (within 24hrs) samples	13
Harvey (Shire of)	Reservoir	HA3/026	Harvey Dam Boat Ramp	-33.081085, 115.953328	1. Program	2014-2018	31	60	B	249	29	Moderate	Good (a)		Collect 5-10 rainfall (24-48hrs) samples	13

DBCA = Department of Biodiversity, Conservation and Attractions  
DoT = Department of Transport  
DWER = Department of Water and Environmental Regulation





## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Results Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category	Provisional Class	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2018-2019
<b>South West Region ...</b>																
Manjimup (Shire of)	Inlet	MJ3/010	Walpole Inlet - Jones St Jetty	-34.97782, 116.7247	3. Proposed	2017-2018	3					Not Avail	Not Avail		Provide DoH SIR	13
Manjimup (Shire of) / DBCA	Inlet	MJ3/014	Nornalup Inlet - Sandy Beach	-34.99576, 116.71322	3. Proposed	2017-2018	3					Moderate	Not Avail		Collect 5-10 rainfall (24-48hrs) samples	13
Manjimup (Shire of)	Inlet	MJ3/015	Nornalup Inlet - Coalmine Beach	-34.99012, 116.73653	3. Proposed	2017-2018	3					Moderate	Not Avail		Collect 5-10 rainfall (24-48hrs) samples	13
Manjimup (Shire of)	Pool	MJ3/020	Pemberton Pool	-34.44303, 116.02999	3. Proposed	2017-2018	3					Moderate	Not Avail		Collect 5-10 upstream riverine & rainfall (24-48hrs) samples	13
Manjimup (Shire of) / DBCA	Reservoir	MJ3/021	Big Brook Dam	-34.40591, 116.02678	3. Proposed	2017-2018	3					Low	Not Avail		Annual SIR Review	13
Manjimup (Shire of) / Private	Reservoir	MJ3/022	Karri Valley Resort	-34.42122, 115.86158	3. Proposed	2017-2018	3					Moderate	Not Avail		Collect 5-10 rainfall (24-48hrs) samples	13
Manjimup (Shire of) / Private	Reservoir	MJ3/1811	Fonty's Pool - SE Cnr Pool (near outlet)	-34.28951, 116.06519	3. Proposed	2017-2018	2					Moderate	Not Avail		Collect 5-10 upstream riverine & rainfall (24-48hrs) samples	13
Manjimup (Shire of)	River	MJ3/023	Pemberton Pool South East Corner	-34.44344, 116.02970	3. Proposed	2017-2018	2					Moderate	Not Avail		Collect 5-10 upstream riverine & rainfall (24-48hrs) samples	13
Nannup (Shire of) / DBCA	River	NA3/001	Barrabup Pool - Platform	-33.944341, 115.691157	2. New	2016-2018	4					Moderate	Not Avail		Collect 5-10 upstream riverine & rainfall (24-48hrs) samples	13
Nannup (Shire of) / DBCA	River	NA3/002	Workers Pool - Steps	-33.953875, 115.686802	2. New	2016-2018	4					Moderate	Not Avail		Collect 5-10 rainfall (24-48hrs) samples	13
Nannup (Shire of)	Reservoir	NA3/004	Donnelly River Village Dam	-34.099146, 115.980946	3. Proposed							Not Avail	Not Avail		Provide DoH SIR	13
Nannup (Shire of)	River	NA3/006	Nannup Townsite Bridge	-33.974655, 115.761673	3. Proposed							Not Avail	Not Avail		Provide DoH SIR	13



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Results Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category	Provisional Class	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2018-2019
<b>Wheatbelt Region</b>																
Dandaragan (Shire of) / DoT	Harbour	DA3/006	Jurien Boat Harbour Beach (West)	-30.291149, 115.044075	1. Program	2013-2018	28	40	A	109	29	Moderate	Good (a)		Collect 5-10 rainfall (24-48 hrs) samples	13
Dandaragan (Shire of) / DoT	Harbour	DA3/007	Jurien Boat Harbour Beach (East)	-30.290526, 115.045607	1. Program	2013-2018	29	18	A	58	20	Moderate	Good (a)		Collect 5-10 rainfall (24-48 hrs) samples	13
Dandaragan (Shire of)	Ocean	DA3/013	Dobbyn Park Beach	-30.301367, 115.03697	1. Program	2013-2018	33	2	A	14	11	Moderate	Good (a)		Collect 5-10 rainfall (24-48 hrs) samples	13
Dandaragan (Shire of)	Ocean	DA3/015	Cervantes - Swimming Beach	-30.495617, 115.065755	1. Program	2013-2018	34	240	C	22448	245	Moderate	Poor		Annual SIR Review	13
Dandaragan (Shire of)	Ocean	DA3/016	Cervantes - Jetty/Boat Ramp	-30.491262, 115.068565	1. Program	2013-2018	34	2	A	19	13	Moderate	Good (a)		Annual SIR Review	13
Gingin (Shire of)	River	GG3/001	Moore River - Mouth Beach	-31.352224, 115.499251	1. Program	2013-2018	28	22	A	60	25	Not Avail	Not Avail		Provide DoH SIR	13
Gingin (Shire of)	River	GG3/002	Moore River - Caravan Park	-31.351037, 115.500438	1. Program	2013-2018	28	165	B	305	77	Not Avail	Not Avail		Provide DoH SIR	13
Gingin (Shire of)	River	GG3/003	Moore River - Boat Ramp	-31.351811, 115.502752	1. Program	2013-2018	28	170	B	547	84	Not Avail	Not Avail		Provide DoH SIR	13
Gingin (Shire of)	River	GG3/010	Moore River Desert Boardwalk	-31.01071, 115.3279	1. Program	2013-2018	28	210	C	341	91	Not Avail	Not Avail		Provide DoH SIR	13
Gingin (Shire of) / DBCA	Ocean	GG3/011	Grace Darling Park Bch	-31.0246, 115.3282	3. Proposed							Not Avail	Not Avail		Provide DoH SIR	13
Gingin (Shire of) / DBCA	Ocean	GG3/012	Harold Park Bch	-31.010732, 115.327557	3. Proposed							Not Avail	Not Avail		Provide DoH SIR	13



## Recreational Waters Bacterial (Enterococci) Monitoring Program Site Status Overview 2018 - Regional Local Government Authorities

Local Government Authority (LGA)/ Managing Authority (MA)	Water Body	Site Code	Site Name	GPS Deci-degrees	Monitoring Category	Results Years	No. Samples	95th %tile	Microbial Assess Category (MAC)	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assess Category	Provisional Class	Beach Grade Website Icon	LGA/ MA Sanitary Inspection Report (SIR) Status Actions	Min No. Samples Rqd 2018-2019
<b>Wheatbelt Region</b>																
Narrogin (Shire of)	Reservoir	NG3/001	Railway Dam - South	-32.947662, 117.178997	3. Proposed							Not Avail	Not Avail		Provide DoH SIR	13
Narrogin (Shire of)	Reservoir	NG3/002	Railway Dam - North	-32.947225, 117.179656	3. Proposed							Not Avail	Not Avail		Provide DoH SIR	13
West Arthur (Shire of) / DBCA, DoT	Lake	AW3/001	Lake Towerrinning - Jetty 1	-33.583888, 116.791518	1. Program	2013-2018	34	700	D	2526	357	Moderate	Poor		Collect 5-10 rainfall (24-48hrs) samples	13
West Arthur (Shire of) / DBCA, DoT	Lake	AW3/002	Lake Towerrinning - Caravan Park	-33.588671, 116.78572	1. Program	2013-2018	30	740	D	2110	338	Not Avail	Not Avail		Provide DoH SIR	13
Wickepin (Shire of)	Lake	WI3/001	Yealering Lake Swimming Hole - NE Corner	-32.596442, 117.634081	3. Proposed							Moderate	Not Avail		Collect 5-10 rainfall (24-48hrs) samples	13
Wickepin (Shire of)	Lake	WI3/006	Yealering Lake Swimming Hole - End of Jetty	-32.595164, 117.627225	3. Proposed							Moderate	Not Avail		Collect 5-10 rainfall (24-48hrs) samples	13
York (Shire of)	Reservoir	YO3/007	WhiteGum Farm Dam	-31.866532, 116.939709	3. Proposed							Not Avail	Not Avail		Provide DoH SIR	13

DBCA = Department of Biodiversity, Conservation and Attractions  
DoT = Department of Transport  
DWER = Department of Water and Environmental Regulation