

Recreational Waters Bacterial (Enterococci) Water Quality Sampling Program Site Status Report October 2013: Garden Island

Site Code	Managing Authority	Site Name	Result Years	No. Samples	95th %tile	Microbial Assess Category	1-off Trigger Level (99th %tile)	2-in-a-row Trigger Level (90th %tile)	Sanitary Assessment Category (SAC)	SAC Key Factor	Min No. Samples Required 2013-2014	SAC Status Comments	Provisional Classification	Provisional Colour
EV3/740	Department of Defence	Careening Bay	2005-2010	48	2	A	140	1	N/A		0	N/A	N/A	Green
EV3/741	Department of Defence	Cliff Head	2005-2010	46	12	A	140	10	Moderate	Rainfall	13	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green
EV3/742	Department of Defence	Pig Trough Bay	2005-2010	48	2	A	140	1	Moderate	Rainfall	13	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green
EV3/743	Department of Defence	Herring Cove	2005-2010	47	2	A	140	10	Moderate	Rainfall	13	Collect 5 rainfall (within 24hrs) samples	Good (a)	Green